





The Little League building at Clapp Park. Note the deteriorating fascia boards at the roof line and the weathered exterior siding.



Opposite side of building with more rotting fascia board.



A close-up of the damage to the fascia boards.



Interior scoreroom ceiling water damage.